

MEMORANDUM

July 8, 2020

TO: Reclamation District No. 756

FROM: Nathan Hershey

SUBJECT: July 2020 Engineer's Report

Described below are the engineering items to be discussed at your July 8, 2020 meeting.

Subventions 2018-19 – The District submitted an application for participation in the Program in the amount of \$845,000. \$12 million has been approved for Program funding for FY 2018-19, consistent with recent previous years. The District's final claim was submitted in the amount of \$253,623.03. The District received reimbursement in the amount of \$172,142.

Subventions 2019-20 – The District submitted an application for participation in the Program in the amount of \$750,000. DWR has lowered the Program funding amount to \$10 million for FY 2019-20.

Subventions 2020-21 – The District submitted an application for participation in the Program in the amount of \$1,595,000. \$12 million has been approved for Program funding for FY 2020-21.

Annual Maintenance – Attached are the current maintenance items we are tracking. We are developing a maintenance project to address the items recommended for repair.

Special Projects – A letter was submitted to DWR requesting reconsideration of the decision to withdraw the funding agreement for the levee setback and habitat enhancement project on the west levee. We are awaiting a response.

We received a fully executed funding agreement for the design portion of the Directed Action project to rehabilitate the north levee. We have requested an advance of funds from DWR. Work is mostly on hold until we receive the advance of funds.

Five Year Plan – Work on the Five-Year Plan is currently in progress. A draft of the plan has been distributed via email and we have incorporated many of the comments received to date. We have also sent a draft to DWR staff for review and comment. The Plan must be complete by the end of 2020.

SB 88 – MBK prepared a Report to update last year's experiment summary report, which has been finalized to include MWD's comments. Work under Phase 3 of the measurement experiment (Feb 2020 through Feb 2021) is underway, as outlined in the approved Request for Additional Time.

Phase 3 efforts primarily involve installing 8 additional flange magnetic meters on the water side of the highest use siphons, with at least one flow meter on each island. MWD has recently obtained funding approvals for Phase 3 and is currently reviewing quotes for the new equipment. After the invoices are submitted, there is a 6-week lead time for new equipment to be delivered. MBK is compiling installation information from various contractors to prepare for receipt of the new equipment. Irrigation on Bacon and

RD 756
Engineer's Report
Page 2

Bouldin Islands has begun, and MBK has scheduled field visits in July to both islands to check existing meters and conduct portable meter tests on running siphons.

The Delta Measurement Experiment Consortium has scheduled its next meeting for July 15, 2020. The meeting will include a presentation by the Delta Water Master's office for a proposed work plan for the Consortium's development of a Delta-wide Alternative Compliance Plan. MBK has not received any updates on the status of the Open ET beta testing.

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 7/1/2020

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
23	Low	2/11/2017	JaimeBarajas	Station 859	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	25 LF core trench along WS hinge to depth of 8'; no pipe or water encountered; backfilled with native material.
24	Low	2/11/2017	JaimeBarajas	Station 924+10	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	40 LF core trench along WS hinge to depth of 8'; encountered water seeping from landside trench wall at 8' depth; backfilled with native and imported dry fill; Drainage ditch to be cut along Caltrans access roadway from Sta 926 to Sta 2 to relieve ponding. Work to be done by Sierra Cattle.
								8/14/17 - Waterside top of pipe = 7.2; 100 yr. flood = 7.6; 12" siphon; pipe is low;
34	Low	2/20/2017	NateHershey	Station 813	Encroachment	Siphon may be low	Monitor	Continue to Monitor
						Cracking in LS Slope; seepage and		Monitor and discuss repair; 10/23/17 Levee crown trenched; no encroachments located, Area to be graded and prepared for flood season; will proceed under Special Projects upon receipt of PFA. 12/4/17 -
41	Medium	3/28/2017	RalphHeringer	Station 544-549	Crack	cattails at toe	Monitor	grading complete

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 7/1/2020

	.				_			
IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
								Reviewed the site area. Area
								appears to be moving again -
								not as dramatic as in 2017, but
								it appears to be along the
								same fault lines. Seepage
								observed exiting the surface.
								Recommend performing an
								updated survey and
41.1		4/24/2020	NateHershey					developing an action plan.
53	Medium	8/11/2017	NateHershey	Station 324	Seepage	Seepage at toe of 3 to 1 slope	Monitor	Monitor
		-, , -	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		3.5.0.5			Monitor; The hole is shallow at
54	Medium	8/11/2017	NateHershey	Station 336	Seepage		Monitor	about 1-2 inches deep.
			·		. •			·
						Longitudinal crack on land side		Investigate and monitor; It's
						slope near toe of Levee. Crack		clear to me that there is
						runs several hundred feet parallel		differential settling after slope
63	Medium	3/23/2018	RussRyan	Station 72	Crack	to Levee road. See photos.	Repair	vegitation was cleared.
						Adjacent to Duck Club office on		Min. Fill material;Need to
						Levee slope water side. Appears		investigate extent of hole and
						to be possible Beaver Den		fill in with Levee backfill
65	Medium	5/8/2018	RussRyan	Station 710	RodentActivity	discovery during low tide.	Repair	material/rock.
								Two levee penetrations, one
						Possible beaver den by district		on top of other. WS slope
65.1	Medium	6/19/2018	AndrewReece	Station 712+00	RodentActivity	office, west of tree on ws slope	Repair	sloughing.
				Land side within 150		Bouldin Island - West stretch		
				foot Levee footprint.		length adjacent to Mokelumne		
				See attached phots.		River. See attached photos for		
74	Low	1/5/2019	RussRyan	Low wet areas.	Other,Sinkhole	exact location.	Investigate	See notes above.
0.5		4/4/2046	NATAL AND LANG.	70.00.00.00	Glass Island	sloughing on water side for about		
85	Low	4/1/2019	MichaelNishimura	79+00-80+00	Sloughing	100 feet, cracking at hinge	Monitor	

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 7/1/2020

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
						Seepage between toe road and		
						seepage ditch appeared last		2
						week. Does not appear to be		District (Dave, Russ, Ralph) to
						tidally influenced and a point		review site on 5/10.
						source was not located.		Exploratory trenching will
						Additional minor wet spots		likely be required. Perform
				Sta 845+00 to 846+00		observed between Sta 841+00		trenching when convenient as
				between toe road and		and 843+00. No known history of		long as site does not change or
86	Medium	5/7/2019	Brian Janowiak	seepage ditch	Seepage	seepage at this location.	Repair	worsen.
		_ / /						
86.1		5/10/2019						Looks like seepage is drying up.
88	Low	6/7/2019	Dave Forkel	Sta 382+00	Seepage	Seepage on side of levee.	Investigate	
	_					sloughing and possible rodent		big rock and might be eroding,
93	Medium	9/26/2019	Andy Reece	693+00	Sloughing, RodentActivity	den	Investigate	possible beaver as well
						Area along lower toe near		
						seepage ditch by Floeida tip		
94	Low	9/27/2019	Brian Janowiak	Lower toe	Other, Settlement	appears to have settled.	Monitor	
						Abandoned houseboat almost		
						completely		
95	Medium	3/16/2020	DaveForkel	Sta 500+00	Other	destroyed	Monitor	Sheriff contacted
96	Medium	4/22/2020	RussRyan	Between 630 and 640	Seepage	Appears to be seepage	Investigate	
97	Medium	4/24/2020	NateHershey	Station 536+25	Erosion	Eroded waterside slope, 60LF +/-	Repair	