

MEMORANDUM

January 13, 2021

TO: Reclamation District No. 756

FROM: Nathan Hershey

SUBJECT: January 2021 Engineer's Report

Described below are the engineering items to be discussed at your January 13, 2021 meeting.

Subventions 2019-20 – The District submitted an application for participation in the Program in the amount of \$750,000. DWR has lowered the Program funding amount to \$10 million for FY 2019-20. The District submitted a final claim in the amount of \$213,176.91.

Subventions 2020-21 – The District submitted an application for participation in the Program in the amount of \$1,595,000. \$12 million has been approved for Program funding for FY 2020-21.

Annual Maintenance – Attached are the current maintenance items we are tracking.

Regional Flood Fight Supply Depot – The District has signed a MOA with Sacramento County to move forward with development of a regional flood fight supply depot. We are working on a site layout and the logistics of developing the depot.

Special Projects – DWR has renewed the offer of State funding for the levee setback and habitat enhancement project on the west levee. The District responded with an acceptance letter and we are waiting to receive the funding agreements for signature.

The District received an advance of funds for design of the Directed Action project to rehabilitate the north levee. We have started work on the design and will be moving forward in anticipation of construction. The District will need to consider a variety of issues, including availability and location of onsite borrow material, structure/encroachment demolition, and other issues that may result in an impact to the landowner and/or their tenants.

Five Year Plan – Work on the Five-Year Plan is currently in progress. A draft of the plan has been distributed via email and we have incorporated many of the comments received to date. We have also sent a draft to DWR staff for review and comment. DWR has extended the expiration date of the funding agreements to December 31, 2021.

SB 88 – Work under Phase 3 of the measurement experiment (Feb 2020 through Feb 2021) is underway, as outlined in the approved Request for Additional Time. Phase 3 efforts primarily involve installing 8 additional flange magnetic meters on the water side of the highest use siphons, with at least one flow meter on each island. MWD has purchased the equipment and set up a bid process for equipment installation.

Since the last update, MBK conducted a field visit to Bouldin Island to conduct portable flow meter tests at siphons running for winter flooding. Tests at Siphons No. 39 and 40 confirmed that telemetry will be

RD 756
Engineer's Report

January 13, 2021
Page 2

required at these siphons for strict compliance with the Measurement Regulation. MBK also checked existing equipment and downloaded data from existing equipment. No new issues with the equipment were observed during the field visit.

Current direction by MWD is to proceed with a combination of strict compliance and developing a MWD Alternative Compliance Plan. In order to develop this plan, MWD submitted a Request for Additional Time on December 21, 2020. MWD was notified by the Office of the Delta Watermaster on December 29, 2020 that the Request was accepted.

Development of the Delta-wide ACP by the Delta Measurement Experiment Consortium to utilize Open ET for measuring and reporting diversions continues. MBK and MWD will continue to participate in the Consortium and provide feedback on the future development of this ACP as needed. The next Consortium meeting is scheduled for January 28, 2021.

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 1/8/2021

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
								25 LF core trench along WS
								hinge to depth of 8'; no pipe or
						Boil on lower levee slope/toe;		water encountered; backfilled
23	Low	2/11/2017	JaimeBarajas	Station 859	Boil	running at high tide	Monitor	with native material.
								40 LF core trench along WS
								hinge to depth of 8';
								encountered water seeping
								from landside trench wall at 8'
								depth; backfilled with native
								and imported dry fill; Drainage
								ditch to be cut along Caltrans
								access roadway from Sta 926 to
						Boil on lower levee slope/toe;		Sta 2 to relieve ponding. Work
24	Low	2/11/2017	JaimeBarajas	Station 924+10	Boil	running at high tide	Monitor	to be done by Sierra Cattle.
								8/14/17 - Waterside top of pipe
								= 7.2; 100 yr. flood = 7.6; 12"
								siphon; pipe is low; Continue to
34	Low	2/20/2017	NateHershey	Station 813	Encroachment	Siphon may be low	Monitor	Monitor
								Monitor and discuss repair;
								10/23/17 Levee crown
								trenched; no encroachments
								located, Area to be graded and
								prepared for flood season; will
								proceed under Special Projects
						Cracking in LS Slope; seepage and		upon receipt of PFA. 12/4/17 -
41	Medium	3/28/2017	RalphHeringer	Station 544-549	Crack	cattails at toe	Monitor	grading complete

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 1/8/2021

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
								Reviewed the site area. Area
								appears to be moving again -
								not as dramatic as in 2017, but
								it appears to be along the same
								fault lines. Seepage observed
								exiting the surface.
								Recommend performing an
								updated survey and developing
41.1		4/24/2020	NateHershey					an action plan.
53	Medium	8/11/2017	NateHershey	Station 324	Seepage	Seepage at toe of 3 to 1 slope	Monitor	Monitor
		- 1 1						Monitor; The hole is shallow at
54	Medium	8/11/2017	NateHershey	Station 336	Seepage		Monitor	about 1-2 inches deep.
						Langita divalance la collega dei de		lavoration to an electrical describer at the
						Longitudinal crack on land side		Investigate and monitor; It's
						slope near toe of Levee. Crack		clear to me that there is
63	Medium	3/23/2018	DuccDyon	Station 72	Crack	runs several hundred feet parallel	Donair	differential settling after slope
63	Medium	3/23/2018	RussRyan	Land side within 150	Crack	to Levee road. See photos. Bouldin Island - West stretch	Repair	vegitation was cleared.
				foot Levee footprint.		length adjacent to Mokelumne		
				See attached phots.		River. See attached photos for		
74	Low	1/5/2019	RussRyan	Low wet areas.	Other,Sinkhole	exact location.	Investigate	See notes above.
/ -	LOW	1/3/2013	Russityan	Low wet areas.	Other, Sinkhole	CAUCE IOCATION.	IIIVCStigate	See notes above.
						Seepage between toe road and		
						seepage ditch appeared last week.		
						Does not appear to be tidally		District (Dave, Russ, Ralph) to
						influenced and a point source was		review site on 5/10.
						not located. Additional minor wet		Exploratory trenching will likely
				Sta 845+00 to 846+00		spots observed between Sta		be required. Perform trenching
				between toe road and		841+00 and 843+00. No known		when convenient as long as site
86	Medium	5/7/2019	Brian Janowiak	seepage ditch	Seepage	history of seepage at this location.	Repair	does not change or worsen.
86.1		5/10/2019						Looks like seepage is drying up.
88	Low	6/7/2019	Dave Forkel	Sta 382+00	Seepage	Seepage on side of levee.	Investigate	
						Area along lower toe near		
		0/27/2212	D		011 6 111	seepage ditch by Floeida tip		
94	Low	9/27/2019	Brian Janowiak	Lower toe	Other, Settlement	appears to have settled.	Monitor	

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 1/8/2021

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
						Abandoned houseboat almost		
						completely		
95	Medium	3/16/2020	DaveForkel	Sta 500+00	Other	destroyed	Monitor	Sheriff contacted
96	Medium	4/22/2020	RussRyan	Between 630 and 640	Seepage	Appears to be seepage	Investigate	
						An 18" diameter pot hole on levee		Will need to investigate extent
				Between Sta 20+00		crest road closer to waterside		of below surface voids below
99	Medium	7/28/2020	RussRyan	and St 40+00.	Sinkhole	slope.	Repair	sink.
						Waterside crack about 100 ft		
104	Medium	11/19/2020	DaveForkel	Sta 426+00	Sloughing	total, spread over 3-4 sites	Repair	
						Levee crest road crack (towards		
						water side). Crack length is about		
				Bouldin Island (see		7 step paces (Russ Ryan) and		
106	Medium	12/17/2020	RussRyan	photo for location)	Crack	depth is unknown.	Monitor	
						Just inside levee footprint on land		
						side of toe drain there water		
						ponding. Was there prior to any		
107	Medium	12/17/2020	RussRyan	See photos	Seepage	rain this season during dry period.	Monitor	See photos taken on site.