

MEMORANDUM

January 18, 2023

TO: Reclamation District No. 756

FROM: Nathan Hershey

SUBJECT: **January 2023 Engineer's Report**

Described below are the engineering items to be discussed at your January 18, 2023 meeting.

Subventions 2021-22 – The District submitted an application for participation in the Program in the amount of \$631,000. An additional \$2 million was approved by the Central Valley Flood Protection Board, for a total of \$12 million approved for the Program for FY 2021-22. A final claim was submitted in the amount of \$292,577.83.

Subventions 2022-23 – The District submitted an application for participation in the Program in the amount of \$631,000. \$12 million was approved by the Central Valley Flood Protection Board for the Program for FY 2022-23.

Annual Maintenance – Attached are the current maintenance items we are tracking.

Regional Flood Fight Supply Depot – The security fence, gates, screen, barbed wire, and razor wire have all been installed, completing the construction of the flood fight supply depot.

Special Projects – Construction of the Directed Action project to rehabilitate the north levee (BO-19-1-SP) is in progress. The Contractor has performed structure demolition, tree removal, and has trenched the seepage site at Station 856+00 to 857+00. We are working with the Contractor on siphon pipe procurement and the start of next construction season's activities.

Five Year Plan – Work on the Five-Year Plan is currently in progress. DWR has extended the expiration date of the funding agreements to March 31, 2023. We are working to address DWR's comments and finalize the Plan.

SB 88 – Work under Phase 4 of the measurement experiment is complete. All phase 4 meters have been installed and have been certified by MBK Engineers. Data is now being collected at 38 sites across all four islands.

Of all 25 meters installed, only one (Holland Tract Siphon No. 1) was unable to be properly programmed and connected to the Wildeye telemetry system. MBK is still investigating this issue with the flow meter manufacturer (McCrometer).

Flow meters for the remaining siphons will be installed over the next two years. MBK is obtaining quotes for the equipment required at the approximately 50 remaining sites. In addition, MBK is identifying any sites that need to be tested for asbestos or tar coating. MBK and MWD will work with Bovee Environmental Management to test sites that are suspected to contain asbestos or a tar coating on the pipe exterior. Any sites

that test positive for these hazardous materials will be abated by W.C. Maloney prior to any flow meter installation.

MWD and the RDs are in compliance for calendar year 2023 under an approved extension of time. The extension was approved by the Delta Watermaster on January 13th, 2022 and will expire on January 1st, 2024. The extension of time included a Plan for Compliance which provides details regarding the methods to estimate diversions on siphons without flow meters and provides a measurement equipment installation schedule. MWD currently anticipates that installing all the flow meters will take five years. Therefore, MBK has provided cost estimates for flange magnetic meters with telemetry equipment installed on the water side of all active siphons.

Development of the Delta-wide ACP by the Delta Measurement Experiment Consortium to utilize Open ET for measuring and reporting diversions continues. Place of use polygons for each island have been completed and will be used in conjunction with Open ET to report on diversions. MBK and MWD continue to participate in the Consortium.

Reclamation District No. 756 Bouldin Island

Issue Tracking Summary

1/16/2023

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
23	Low	2/11/2017	JaimeBarajas	Station 859	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	25 LF core trench along WS hinge to depth of 8'; no pipe or water encountered; backfilled with native material.
24	Low	2/11/2017	JaimeBarajas	Station 924+10	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	40 LF core trench along WS hinge to depth of 8'; encountered water seeping from landside trench wall at 8' depth; backfilled with native and imported dry fill; Drainage ditch to be cut along Caltrans access roadway from Sta 926 to Sta 2 to relieve ponding. Work to be done by Sierra Cattle.
34	Low	2/20/2017	NateHershey	Station 813	Encroachment	Siphon may be low	Monitor	8/14/17 - Waterside top of pipe = 7.2; 100 yr. flood = 7.6; 12" siphon; pipe is low; Continue to Monitor
41	Medium	3/28/2017	RalphHeringer	Station 544-549	Crack	Cracking in LS Slope; seepage and cattails at toe	Monitor	Monitor and discuss repair; 10/23/17 Levee crown trenched; no encroachments located, Area to be graded and prepared for flood season; will proceed under Special Projects upon receipt of PFA. 12/4/17 - grading complete

Reclamation District No. 756 Bouldin Island

Issue Tracking Summary

1/16/2023

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
41.1		4/24/2020	Nate Hershey					Reviewed the site area. Area appears to be moving again - not as dramatic as in 2017, but it appears to be along the same fault lines. Seepage observed exiting the surface. Recommend performing an updated survey and developing an action plan.
53	Medium	8/11/2017	NateHershey	Station 324	Seepage	Seepage at toe of 3 to 1 slope	Monitor	Monitor
54	Medium	8/11/2017	NateHershey	Station 336	Seepage		Monitor	Monitor; The hole is shallow at about 1-2 inches deep.
63	Medium	3/23/2018	RussRyan	Station 72	Crack	Longitudinal crack on land side slope near toe of Levee. Crack runs several hundred feet parallel to Levee road. See photos.	Repair	Investigate and monitor; It's clear to me that there is differential settling after slope vegetation was cleared.
74	Low	1/5/2019	RussRyan	Land side within 150 foot Levee footprint. See attached photos.	Other,Sinkhole	Bouldin Island - West stretch length adjacent to Mokelumne River. See attached photos for exact location.	Investigate	See notes above.
88	Low	6/7/2019	DaveForkel	Sta 382+00	Seepage	Seepage on side of levee.	Investigate	
94	Low	9/27/2019	BrianJanowiak	Lower toe	Other	Area along lower toe near seepage ditch by Florida tip appears to have settled.	Monitor	
96	Medium	4/22/2020	RussRyan	Between 630 and 640	Seepage	Appears to be seepage	Investigate	
104	Medium	11/19/2020	DaveForkel	Sta 426+00	Sloughing	Waterside crack about 100 ft total, spread over 3-4 sites	Repair	
106	Medium	12/17/2020	RussRyan	Station 102	Crack	Levee crest road crack (towards water side). Crack length is about 7 step paces (Russ Ryan) and depth is unknown.	Monitor	
107	Medium	12/17/2020	RussRyan	Station 630	Seepage	Just inside levee footprint on land side of toe drain there water ponding. Was there prior to any rain this season during dry period.	Monitor	See photos taken on site.

Reclamation District No. 756 Bouldin Island

Issue Tracking Summary

1/16/2023

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
108	Medium	7/8/2021	RussRyan	Station 90	Crack	Cracking observed on landside slope. Unclear if this is a result of the earthquake event.	Monitor	
109	Medium	7/8/2021	RussRyan	Station 226	Sloughing	Potential landside settlement on toe berm. Unclear if this is earthquake related.	Monitor	
110	Medium	7/8/2021	RussRyan	Station 503	Sloughing	Landside disturbance. Unclear if earthquake related or due to sheep activity.	Monitor	
112	Medium	1/10/2022	DaveForkel	Sta 345+00	Crack	Erosion in top of the levee at crack.	Repair	Should be excavated and repaired.
113	Medium	1/14/2022	RussRyan	Sta 105	Crack	Longitudinal crack located on levee crest road on hinge point to water side slope. The crack was measured with tape measured at 49 ft/50 ft total length along 4 segments.	Repair	Need to repair as future rainy weather may open cracks further that could potentially lead to sloughing into river.
115	High	1/14/2022	RussRyan	Sta 96	RodentActivity	Land side approx 3-5 feet below crest road elevation. See attached photo map.	Repair	Appears a deep rodent den.
116	Medium	2/21/2022	RussRyan	camp 5 at pilot project in	Seepage	Noticeable standing water at toe of levee at the same 2017 slippage event.	Investigate	Need Geotech investigation and assessments.

Reclamation District No. 756 Bouldin Island

Issue Tracking Summary

1/16/2023

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
117	Low	2/23/2022	RussRyan	Location is landside off west levee (Bouldin Island) and south of Hwy 12	Seepage	Landside water ponding presenting at toe of levee.	Investigate	Roughly an estimated 30 feet by 10 feet. Dimensions need to be verified in field investigation.
119	Medium	7/7/2022	AndrewReece	Station 39	Crack		Repair	
120	Medium	5/19/2022	NateHershey	Station 856	Seepage	Seepage and ponding water reported at location of old toe ditch near Station 856. Confirmed in field (see photos).	Monitor	Recommend monitoring and repairing as part of Special Projects work on north levee. Continue to monitor and adjust if necessary.
121	Medium	10/14/2022	NateHershey	Station 33	Seepage	Seepage observed periodically on toe of levee. Seems to come and go, sometimes difficult to tell if it is seepage or ponding water. Observations suggest it is likely seepage that periodically appears during times of high water.	Investigate	Trenching scheduled for late October/early November.
122	High	1/4/2023	AndrewReece	Station 492	Boil	Boil observed near ramp. Appears to have recently started. Water flowing down ramp. Need to stabilize.	Repair	
123	High	1/4/2023	AndrewReece	Station 498	Erosion	Waterside slope eroding in several locations.	Repair	
124	Medium	1/4/2023	AndrewReece	Station 555	Erosion	Eroded slope	Repair	