

MEMORANDUM

December 16, 2020

TO: Reclamation District No. 756

FROM: Nathan Hershey

SUBJECT: December 2020 Engineer's Report

Described below are the engineering items to be discussed at your December 16, 2020 meeting.

Subventions 2019-20 – The District submitted an application for participation in the Program in the amount of \$750,000. DWR has lowered the Program funding amount to \$10 million for FY 2019-20. The District submitted a final claim in the amount of \$213,176.91.

Subventions 2020-21 – The District submitted an application for participation in the Program in the amount of \$1,595,000. \$12 million has been approved for Program funding for FY 2020-21.

Annual Maintenance – Attached are the current maintenance items we are tracking.

Regional Flood Fight Supply Depot – We have been working with DWR and Sacramento County on a regional flood fight supply depot concept. DWR has distributed grant funds to Sacramento County to administer on behalf of the other Delta counties. Conceptually, a participating local agency would sign a MOU with Sacramento County to construct and maintain a regional supply depot. Sacramento County would order and deliver the supplies and equipment, and the local entity would manage the facility. Bouldin Island is an attractive candidate for the central Delta due to its proximity to the Highway 12 corridor. We are exploring the opportunity to see if it makes sense for the District to move forward.

Special Projects – DWR has renewed the offer of State funding for the levee setback and habitat enhancement project on the west levee. The District responded with an acceptance letter and we are waiting to receive the funding agreements for signature.

We received a fully executed funding agreement for the design portion of the Directed Action project to rehabilitate the north levee. We have requested an advance of funds from DWR. Work is mostly on hold until we receive the advance of funds.

Five Year Plan – Work on the Five-Year Plan is currently in progress. A draft of the plan has been distributed via email and we have incorporated many of the comments received to date. We have also sent a draft to DWR staff for review and comment. DWR has extended the expiration date of the funding agreements to December 31, 2021.

Delta Stewardship Council – In October, the Delta Stewardship Council (DSC) staff provided interested stakeholders an overview of the risk analysis component of the Delta Levees Investment Strategy (DLIS). Updates to the DLIS risk analysis include the incorporation of new data (2017 DWR LiDAR, updated flood hydrology and updated water surface elevations). The DSC's goal is to improve how the fragility curves represent Delta levee conditions and failure modes. DSC staff provided a dashboard tool to review specific

island/tract data and has requested feedback by the end of November. MBK collaborated with KSN, Hultgren-Tillis and Engeo and submitted written comments. We are continuing our coordination effort with DSC staff.

SB 88 – Work under Phase 3 of the measurement experiment (Feb. 2020 through Feb. 2021) is underway, as outlined in the approved Request for Additional Time. Phase 3 efforts primarily involve installing 8 additional flange magnetic meters on the water side of the highest use siphons, with at least one flow meter on each island. MWD is currently processing the equipment quotes and is setting up a bid process for equipment installation. As a result of the issues with the Ultra Mag meter at Bouldin Island Siphon No. 24, the equipment quotes include additional enclosures for the converter units at each Ultra Mag meter site, which is anticipated to prevent moisture intrusion into the units. The replacement converter for Bouldin Island Siphon No. 24 has arrived and reinstallation is expected to take place when the other equipment for Phase 3 is installed.

Since the last update, MBK conducted field visits to Holland Tract and Webb Tract to conduct portable flow meter tests at siphons running for winter flooding. Earlier this month MBK also visited Bacon Island to conduct portable flow meter tests, check existing equipment, and download data from existing equipment. Current direction by MWD is to proceed with a combination of strict compliance and developing a MWD Alternative Compliance Plan. Regardless of the approach for compliance, MWD will need to submit a Request for Additional Time, prior to the expiration of the current one on December 31, 2020 for another year of time. MBK provided a draft Request which MWD is finalizing and submitting.

Development of the Delta-wide ACP by the Delta Measurement Experiment Consortium to utilize Open ET for measuring and reporting diversions continues. MBK and MWD will continue to participate in the Consortium and provide feedback on the future development of this ACP as needed.

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 12/11/2020

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
23	Low	2/11/2017	JaimeBarajas	Station 859	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	25 LF core trench along WS hinge to depth of 8'; no pipe or water encountered; backfilled with native material.
24	Low	2/11/2017	JaimeBarajas	Station 924+10	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	40 LF core trench along WS hinge to depth of 8'; encountered water seeping from landside trench wall at 8' depth; backfilled with native and imported dry fill; Drainage ditch to be cut along Caltrans access roadway from Sta 926 to Sta 2 to relieve ponding. Work to be done by Sierra Cattle.
34	Low	2/20/2017	NateHershey	Station 813	Encroachment	Siphon may be low	Monitor	8/14/17 - Waterside top of pipe = 7.2; 100 yr. flood = 7.6; 12" siphon; pipe is low; Continue to Monitor
41	Medium	3/28/2017	RalphHeringer	Station 544-549	Crack	Cracking in LS Slope; seepage and cattails at toe	Monitor	Monitor and discuss repair; 10/23/17 Levee crown trenched; no encroachments located, Area to be graded and prepared for flood season; will proceed under Special Projects upon receipt of PFA. 12/4/17 - grading complete

Reclamation District No. 756 Bouldin Island Issue Tracking Summary 12/11/2020

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
								Reviewed the site area. Area
								appears to be moving again -
								not as dramatic as in 2017, but
								it appears to be along the same
								fault lines. Seepage observed
								exiting the surface.
								Recommend performing an
41.1		4/24/2020	Natallanahau					updated survey and developing
41.1	NA o divino	4/24/2020	NateHershey	Ctation 224	Caarana	Connect the of 2 to 1 class	Monitor	an action plan.
53	Medium	8/11/2017	NateHershey	Station 324	Seepage	Seepage at toe of 3 to 1 slope	Monitor	Monitor Monitor; The hole is shallow at
54	Medium	8/11/2017	NateHershey	Station 336	Seepage		Monitor	about 1-2 inches deep.
54	Mediaiii	8/11/2017	Nateriersney	Station 550	Seepage		Wildfilledi	about 1-2 inches deep.
						Longitudinal crack on land side		Investigate and monitor; It's
						slope near toe of Levee. Crack		clear to me that there is
						runs several hundred feet parallel		differential settling after slope
63	Medium	3/23/2018	RussRyan	Station 72	Crack	to Levee road. See photos.	Repair	vegitation was cleared.
			, ,	Land side within 150		Bouldin Island - West stretch		
				foot Levee footprint.		length adjacent to Mokelumne		
				See attached phots.		River. See attached photos for		
74	Low	1/5/2019	RussRyan	Low wet areas.	Other, Sinkhole	exact location.	Investigate	See notes above.
						Seepage between toe road and		
						seepage ditch appeared last week.		
						Does not appear to be tidally		District (Dave, Russ, Ralph) to
						influenced and a point source was		review site on 5/10.
						not located. Additional minor wet		Exploratory trenching will likely
				Sta 845+00 to 846+00		spots observed between Sta		be required. Perform trenching
		= /= /c - · ·		between toe road and		841+00 and 843+00. No known		when convenient as long as site
86	Medium	5/7/2019	Brian Janowiak	seepage ditch	Seepage	history of seepage at this location.	Repair	does not change or worsen.
00.1		F /10/2010						Laska lika asanana ia du da sur
86.1 88	Low	5/10/2019 6/7/2019	Dave Forkel	Sta 382+00	Soonaga	Seepage on side of levee.	Investigata	Looks like seepage is drying up.
88	Low	0///2019	Dave Forkel	Sta 382+00	Seepage	seepage on side of levee.	Investigate	

Reclamation District No. 756 Bouldin Island Issue Tracking Summary

12/11/2020

								e: 11 s
IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
						Area along lower toe near		
						seepage ditch by Floeida tip		
94	Low	9/27/2019	Brian Janowiak	Lower toe	Other, Settlement	appears to have settled.	Monitor	
						Abandoned houseboat almost		
						completely		
95	Medium	3/16/2020	DaveForkel	Sta 500+00	Other	destroyed	Monitor	Sheriff contacted
96	Medium	4/22/2020	RussRyan	Between 630 and 640	Seepage	Appears to be seepage	Investigate	
						An 18" diameter pot hole on levee		Will need to investigate extent
				Between Sta 20+00		crest road closer to waterside		of below surface voids below
99	Medium	7/28/2020	RussRyan	and St 40+00.	Sinkhole	slope.	Repair	sink.
						Waterside crack about 100 ft		
104	Medium	11/19/2020	DaveForkel	Sta 426+00	Sloughing	total, spread over 3-4 sites	Repair	