

## **MEMORANDUM**

June 16, 2021

**TO:** Reclamation District No. 756

**FROM:** Nathan Hershey

**SUBJECT:** June 2021 Engineer's Report

Described below are the engineering items to be discussed at your June 16, 2021 meeting.

**Subventions 2019-20** – The District submitted an application for participation in the Program in the amount of \$750,000. DWR has lowered the Program funding amount to \$10 million for FY 2019-20. The District submitted a claim in the amount of \$213,176.91 for the fiscal year.

**Subventions 2020-21** – The District submitted an application for participation in the Program in the amount of \$1,595,000. \$12 million has been approved for Program funding for FY 2020-21.

**Subventions 2021-22** – The District submitted an application for participation in the Program in the amount of \$631,000. DWR has informed us they will be seeking \$10 million for the Program for FY 2021-22.

**Annual Maintenance** – Attached are the current maintenance items we are tracking.

Flood Fight Supplies – The District has an opportunity to acquire flood fight supplies through a DWR grant with San Joaquin County. Details were distributed via email on February 25. Eligible items will be fully reimbursed up to \$15,000 for each participating district. The County has asked districts to submit the reimbursement documentation as soon as possible. The County will be submitting for DWR reimbursement on June 30.

**Regional Flood Fight Supply Depot** – The District has signed a MOA with Sacramento County to move forward with development of a regional flood fight supply depot. We have developed a preliminary site layout and are working on the logistics of developing the depot. We are waiting for Sac County to provide details on the funding available for the site improvements.

**Special Projects** – DWR has renewed the offer of State funding for the levee setback and habitat enhancement project on the west levee. The funding agreement has been fully executed and work on the project may begin.

The District received an advance of funds for design of the Directed Action project to rehabilitate the north levee. The design is progressing and are moving forward in anticipation of construction. We are working through various design related issues and are developing the plans and specifications. The funding agreement has been amended to allow for construction and the amendment has been fully executed.

Five Year Plan – Work on the Five-Year Plan is currently in progress. A draft of the plan has been distributed via email and we have incorporated the comments received to date. We have also sent a draft to

RD 756
Engineer's Report

June 16, 2021
Page 2

DWR staff for review and comment. DWR has extended the expiration date of the funding agreements to December 31, 2021.

SB 88 – Work under Phase 3 of the measurement experiment has been extended and is currently underway. Phase 3 efforts primarily involve installing 8 additional flange magnetic meters on the water side of the highest use siphons, with at least one flow meter on each island. To date the flow meter installations on Bacon Island, Holland Tract, and Webb Tract have been completed. Gornto Ditching plans to finish installing meters on Bouldin Island by June 18th. MBK plans to visit the sites to certify the installed flow meters once all installations are complete. Gornto Ditching will continue to send weekly updates detailing their progress on the installation efforts. The installation of telemetry equipment is currently planned for the weeks of June 18th and June 25th. MBK plans to be present for these installations.

MWD and the RDs are in compliance for calendar year 2021 under an approved extension of time. Current direction by MWD was to proceed with strict compliance. Therefore, MBK has provided cost estimates for flange magnetic meters installed on the water side of all active siphons and developed a draft plan for compliance, which was provided to staff and legal counsel on June 8th. The draft plan for compliance will be refined with specific plans for individual siphons as operational details and legal direction are confirmed.

Development of the Delta-wide ACP by the Delta Measurement Experiment Consortium to utilize Open ET for measuring and reporting diversions continues. RD staff are currently in the process of creating place of use polygons for each of the islands. MBK and MWD continue to participate in the Consortium. The next Consortium meeting has not yet been scheduled.

## Reclamation District No. 756 Bouldin Island Issue Tracking Summary

6/11/2021

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
23	Low	2/11/2017	JaimeBarajas	Station 859	Boil	Boil on lower levee slope/toe; running at high tide	Monitor	25 LF core trench along WS hinge to depth of 8'; no pipe or water encountered; backfilled with native material.
24	Low	2/11/2017	JaimoParaias	Station 024/10	<b>Poil</b>	Boil on lower levee slope/toe;	Monitor	40 LF core trench along WS hinge to depth of 8'; encountered water seeping from landside trench wall at 8' depth; backfilled with native and imported dry fill; Drainage ditch to be cut along Caltrans access roadway from Sta 926 to Sta 2 to relieve ponding. Work
24	Low	2/11/2017	JaimeBarajas	Station 924+10	Boil	running at high tide	Monitor	to be done by Sierra Cattle.
34	Low	2/20/2017	NateHershey	Station 813	Encroachment	Siphon may be low	Monitor	8/14/17 - Waterside top of pipe = 7.2; 100 yr. flood = 7.6; 12" siphon; pipe is low; Continue to Monitor
						Cracking in LS Slope; seepage and		Monitor and discuss repair; 10/23/17 Levee crown trenched; no encroachments located, Area to be graded and prepared for flood season; will proceed under Special Projects upon receipt of PFA. 12/4/17 -
41	Medium	3/28/2017	RalphHeringer	Station 544-549	Crack	cattails at toe	Monitor	grading complete

## Reclamation District No. 756 Bouldin Island Issue Tracking Summary

6/11/2021

IssueID	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
								5 · 1.1 · .
								Reviewed the site area. Area
								appears to be moving again -
								not as dramatic as in 2017, but
								it appears to be along the same
								fault lines. Seepage observed
								exiting the surface.
								Recommend performing an
		4 /2 4 /2 2 2						updated survey and developing
41.1		4/24/2020	NateHershey	0 004		6 60. 4.1		an action plan.
53	Medium	8/11/2017	NateHershey	Station 324	Seepage	Seepage at toe of 3 to 1 slope	Monitor	Monitor
E 4	0.01:	0/44/2047	Niekalianska.	Ct-+: 22C	C			Monitor; The hole is shallow at
54	Medium	8/11/2017	NateHershey	Station 336	Seepage		Monitor	about 1-2 inches deep.
						Longitudinal crack on land side		Investigate and monitor; It's
						slope near toe of Levee. Crack		clear to me that there is
						runs several hundred feet parallel		differential settling after slope
63	Medium	3/23/2018	RussRyan	Station 72	Crack	to Levee road. See photos.	Repair	vegitation was cleared.
03	Medium	3/23/2016	Nussnyaii	Land side within 150	Clack	Bouldin Island - West stretch	керап	vegitation was cleared.
				foot Levee footprint.		length adjacent to Mokelumne		
				See attached phots.		River. See attached photos for		
74	Low	1/5/2019	RussRyan	Low wet areas.	Other,Sinkhole	exact location.	Investigate	See notes above.
88	Low	6/7/2019	Dave Forkel	Sta 382+00	Seepage	Seepage on side of levee.	Investigate	See notes above.
88	LOW	0/7/2019	Dave Forker	3ta 362+00	Seepage	Area along lower toe near	ilivestigate	
						seepage ditch by Floeida tip		
94	Low	9/27/2019	Brian Janowiak	Lower toe	Other, Settlement	appears to have settled.	Monitor	
96	Medium	4/22/2020	RussRyan	Between 630 and 640	Seepage	Appears to be seepage	Investigate	
30	Wicaram	1,22,2020	nassityan	Between 030 and 010	occpage	Waterside crack about 100 ft	mvestigate	
104	Medium	11/19/2020	DaveForkel	Sta 426+00	Sloughing	total, spread over 3-4 sites	Repair	
		, -, -				, , ,		
						Levee crest road crack (towards		
						water side). Crack length is about		
				Bouldin Island (see		7 step paces (Russ Ryan) and		
106	Medium	12/17/2020	RussRyan	photo for location)	Crack	depth is unknown.	Monitor	
			,			·		
						Just inside levee footprint on land		
						side of toe drain there water		
						ponding. Was there prior to any		
107	Medium	12/17/2020	RussRyan	See photos	Seepage	rain this season during dry period.	Monitor	See photos taken on site.